ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
5

Ward Name
Jakkuru

Street ID
W0651, W0645, W0643, W0376

Street Name
NA, 4th Crs, 7th Crs Lakshmi Sagar Lyt

Significant Landmark
Srinivaspura Village

Segment No.
5/C-W0651/S120859

Total Length (m)
276.49

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	172.74	77.622921	13.105047	77.622607	13.103627	RI-A04	W0645
2	103.75	77.623182	13.105977	77.622963	13.105064	W0643	SWD

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone

Job No. / Work Code
005-15-000009

Work Order No.
EE/BTP/BBMP/E-PMT/214/2014-15

Work Order Date
15/01/2015

Period of Extention
60 DAYS

Defect Liability Period From
14/01/2015

Defect Liability Period To
13/01/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
S.K.KESHAVAMURTHY

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.
9902126909

E-Mail ID

Field Inspection Details

Number of Trees	Any Other Information	Name
15		CHANDRAKANTHA

Date of Inspection	Remarks
19/07/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0651, W0645, W0643, W0376

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/07/2016	18/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0651, W0645, W0643, W0376

SE	VASU K M	19/07/2016	18/08/2016	COMPLETED
EE	YARAPPA REDDY	19/07/2016	18/08/2016	COMPLETED
AEE	J N LOKESH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0651, W0645, W0643, W0376

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0699, W0386, W0705, W0689, W0695, W0709	NA, Doddamuniswammppa Lyt, 2nd Crs	PONNAPPA LAYOUT
Segment No.	**Total Length (m)**	
5/C-W0699/S120039	96.63	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	96.63	77.625686	13.103809	77.626542	13.103567	W0695	W0709

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	2000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads & Drains and at Srinivaspura Village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-15-000009
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/214/2014-15	15/01/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
14/01/2015	13/01/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
S.K.KESHAVAMURTHY		0.00
Phone No.	**E-Mail ID**	
9902126909		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0699, W0386, W0705, W0689,

Number of Trees	Any Other Information	Name
5		CHANDRAKANTHA

Date of Inspection	Remarks
19/07/2016	completed

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0699, W0386, W0705, W0689,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/07/2016	18/08/2016	COMPLETED
SE	VASU K M	19/07/2016	18/08/2016	COMPLETED
EE	YARAPPA REDDY	19/07/2016	18/08/2016	COMPLETED
AEE	J N LOKESH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED
AE	CHANDRAKANTH	19/07/2016	18/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0699, W0386, W0705, W0689,